

# PROFORMA FOR THE SAFETY OF SCHOOL BUILDING

## PART - I

(To be filled by the Head of School/Institute)

1. Name of the School **S.M.M.B. Memorial School**
2. Location **Badhni Kalan Distt. Moga**
3. Plot Area **2 Acre**
4. Plinth Area **GF 9481 Sq.Ft., FF 9164 Sq.Ft. , SF 9164 Sq.Ft.  
New GF 9327 Sq.Ft., New FF 9660 Sq.Ft. (Total 46796 Sq.Ft.)**
5. Number of Storey's **Triple Storey + New Double Storey**
6. Year of construction of Building **Old 2011 and new 2014**
7. If the building has been constructed under the supervision of the qualified Engineer, the following details may be given:
  - a) Name of the Engineer with qualification **Hardeep Kumar B E (Civil)**
  - b) Address of the Engineer **Harry Builders and Planners, Moga**
  - c) Set of Structural drawings used in the construction, if available
  - d) Name & Address of Architect with qualification **-----do-----**
8. Whether the building has been constructed for the purpose of
  - a) School **YES / NO**
  - b) Residential purpose and converted for use as a school **YES / NO**
9. Materials used for roofs:
  - a) R.C.C. slabs **YES / NO**
  - b) R.S. Joist & Battons **YES / NO**
  - c) Wooden joists and Battons **YES / NO**
10. Materials used for walls
  - a) Mud Mortar **YES / NO**
  - b) Cement Mortar **YES / NO**
  - c) Lime Mortar **YES / NO**
11. Flooring:
  - a) Conglomerate **YES / NO**
  - b) Terrazo **YES / NO**
  - c) Brick paving **YES / NO**
12. A detailed drawing indicating dimensions of the rooms along with size and location of doors and windows (attached) **Attached**
13. **FOR FIRE SAFETY**
  - a) Weather the width of the staircase is 1.5 Mtr. **YES / NO**
  - b) Weather portable fire extinguisher exists. **YES / NO**
  - d) Weather School building is free from inflammable & toxic material: **YES / NO**
  - e) Weather cooking of food is done at a safe place: **YES / NO**
  - f) Weather any thatch of combustible material has been used: **YES / NO**

14. Required for Fire Protection Arrangements under NBC Part IV  
(For building height less than 15 Mtrs.)
- a) Weather Hose Reel provided: YES / NO ✓
  - b) Weather down corner provided: YES / NO ✓
  - c) Weather automatic sprinkler provide YES / NO ✓
15. Weather underground static water storage tank of capacity 50000 Ltr. (if converted are excess 1600 Sqm. ) YES / NO ✓
16. Weather over head tank of capacity 10000 Ltr. Exists ( in case of hose reel ) 20000 Ltr. YES / NO ✓
17. Weather one electric and one diesel pump of 3 Kg/ cum. Pressure of capacity 1620 LPM. One electric pump of capacity 180 LPM exist near underground static tank: YES / NO ✓
18. Weather a pump 3 Kg/cum pressure & 450/500 LPM exist near over head tank: YES / NO ✓

*Principa*  
Principal

Signature with stamp and seal  
of the school/Institution

**PART - II**

( To be filled by the SDE of the PWD ( B&R ) Department )

1. I have visited the above mentioned school on dated ..... 22-5-18 ..... and have visually inspected it from all angles of safety and find it fit for normal use as School building.
2. In case any addition/alteration or expansion and modification to this building is to be carried out under the supervision of a qualified Engineer and this certificate may be re-obtained after the completion from the undersigned.
3. In case the building is affected by flood or if there is settlement of walls/foundations or sagging of roofs etc. immediate inspection of the undersigned by arrange to check the stability and safety of the building.
4. This building can be safely occupied for normal use upto (indicate year upto which it can be used ) ..... 31-3-19 .....

Sub Divisional Engineer  
PWD ( B&R ) Branch  
Division No. 1  
PWD B & R Br. Moga

ਦਫਤਰ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ: 1 ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਮੋਗਾ  
ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਪੀ.ਡਬਲਯੂ.ਡੀ.ਰੈਸਟ ਹਾਊਸ, ਮੋਗਾ।

ਵੱਲ

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,  
 ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ: 1 ਭ ਤੇ ਮ ਸ਼ਾਖਾ,  
 ਮੋਗਾ।

ਸੇਵਾ ਵਿਖੇ,

ਪ੍ਰਿੰਸੀਪਲ,  
 ਐਸ.ਐਮ.ਐਮ.ਬੀ.ਮੌਮੋਰੀਅਲ ਸਕੂਲ,  
 ਬਧਨੀ ਕਲਾਂ, (ਮੋਗਾ)।

ਨੰ: 159 / ਮਿਤੀ 02/06/18

ਵਿਸ਼ਾ :- ਸਕੂਲ ਦੀ ਇਮਾਰਤ ਸੁਰਖਿਅਤ ਹੋਣ ਸਬੰਧੀ ਸਰਟੀਫਿਕੇਟ ਬਾਬਤ ਸਾਲ 2018-19।

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਦੇ ਸਬੰਧ ਵਿਚ ਆਪ ਜੀ ਦੇ ਸਕੂਲ ਦੀ ਇਮਾਰਤ ਦਾ ਨਿਰੀਖਣ ਸਬੰਧਤ ਜੂਨੀਅਰ ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ ਕੀਤਾ ਗਿਆ ਅਤੇ ਇਮਾਰਤ ਸੁਰਖਿਅਤ ਪਾਈ ਗਈ ਇਸ ਲਈ ਹੁਣ ਇਸ ਸਕੂਲ ਇਮਾਰਤ ਦਾ ਸੁਰਖਿਅਤ ਹੋਣ ਸਬੰਧੀ ਸਰਟੀਫਿਕੇਟ ਸਾਲ 2018-19 ਆਪ ਜੀ ਨੂੰ ਸੂਚਨਾ ਅਤੇ ਅਗਲੇਰੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

ਨੱਥੀ/ ਸਰਟੀਫਿਕੇਟ।

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,  
 ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ 1 ਭ ਤੇ ਮ ਸ਼ਾਖਾ,  
 ਮੋਗਾ।